

## Clammer Hill allotment – entrance

### BACKGROUND

Allotment holders have requested the entrance be upgraded. The ground is very uneven and needs repair and resurfacing. There is a possibility of damage to the underneath of cars using it.

#### Works required:

- Allotment holders given advance notice – access on foot via public footpath.
- Cordon off area.
- Confirm no other services involved. Water highlighted.
- Removal of old driveway by approx. 120mm to 150mm in depth
- Re levelled use existing excavated if possible, in natural slope.
- Top covering to be confirmed, possibly tarmac or concrete.
- Edging into natural grass.
- Concrete/granite edging curve on entrance
- Area approximately 60sqm
- Quote on Concrete and Tarmac options

Company	Total cost Concrete	Total cost Tarmac
Bushy Business	£3,500.00	£5,040.00
Axtell	£7,969.00	£5,769.00
Valley Dean (£320 if concrete edged)	Does not recommend	£6,775.00
Conclusion from all companies that have quoted is that they do not recommend concrete, they do recommend Asphalt with granite edging on road entrance. This ties in with the road and landscape with majority of edging going into grass banks.		

The photograph on the second page of this report does not do justice to the state of disrepair. Councillors are advised to do a site visit before the meeting.

**Recommendation:** to fund this project from the balance of the allotment EMR, amenities EMR and Haslemere Community Fund.

**Recommendation:** Axtell Ltd be instructed to proceed with their quote, subject to approval from Full Council at their next meeting.

