



# HASLEMERE TOWN COUNCIL

## **Lion Green HIP HOP repair**

### **Background:**

In 2022, the bearings were replaced at a cost of £450. When installing, our contractor confirmed that the bushes, the rubberised mechanism to stop excess movement, were badly worn. We were advised by the manufacturer that the HIP HOP has been upgraded and the bushes are no longer available so we will have to replace the whole hub.



**RECOMMENDATION:** Agree to replace the hub, at a cost of £2,105.40 from the play equipment reserve.